


1. In order to “Create a last in 3 surfaces” it is necessary to select the last from the following folder:
 - a. Lasts in other formats
 - b. Manufacturing lasts
 - c. Flattened lasts
2. Which is the next step, after the last in 3 surfaces is created?
 - a. Flatten the last
 - b. Create manufacturing last
 - c. Design a new shoe model
3. Which action is presented in the picture below?
 - a. Mirror the tip toe line on the inside part of the last
 - b. Extend the tip toe line on the inside part of the last
 - c. Extend the vamp line on the inside part of the last



4. What operations can be performed in the menu represented in the picture below?
 - a. Edit piece name and thickness
 - b. Edit piece name, offset, thickness and profile
 - c. Edit piece name, offset, thickness, profile and color

	Offset	Thic...	Profile	I		
Uppers	0	1		<input type="checkbox"/>		
+ Tip	0	2		<input type="checkbox"/>		
+ Vamp	0	1		<input type="checkbox"/>		
+ Tongue	0	1		<input type="checkbox"/>		
+ Outside quarter	0.5	1.5		<input type="checkbox"/>		
+ Inside quarter	0	1.5		<input type="checkbox"/>		
+ Counter	0	2.5		<input type="checkbox"/>		

5. Which bottom part component is active in the picture below?
 - a. Insole
 - b. Sole
 - c. Heel

